UNITED STATES DEPARTMENT OF THE INTERIOR

From A. Fromes DARTE AT ETTEL

NATIONAL PARK SERVICE Washington D.C. 20240

B- 4073 MAGI # 0440732504

HISTORIC PRESERVATION CERTIFICATION

Instructions: Applicant should read the instructions carefully before completing application. No certification may be made upless a concleted application form has been received. Use typewriter or print clearly in dark ink to complete the application form. It additional spaces in Edge to complete Part 1, use the reverse side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropriate State Historic Preservation Officer at anytime during the year.

еррпсыны	ppicanon may be compared to the control of the cont			MARYLAND HISTORI		
PART 1	EVALUATION OF SIGNIFI	CANCE		, .	TRUST	
1. Name of	property: N/A					
	Address of property: 601 S. Fremont Avenue					
Address	2011 101 CAR		(20)	150	0103	
City	historic district in which property is locate	d: County		1111	Zip Code _ 5 _ 5 _ 5	
-		Ridgely's De	light			
Ecertific D decent	ere II request is for: cation (structure contributes to significance ification (structure does not contribute to sent qualification (for donation of easement	significance of the district	conservation purpose	·s).		
601 S	on of Physical Appearance: ructions for map and photograph requirem . Fremont Avenue is a three west. It is a corner row a	story brick stru	cture circa 18			
3. Statemer	nt of Significance: erse side if necessary)	mit with a store	from on the		on reverse)	
fact	The significance of 601 S. I that it is an integral part ht has been certified as eli	of the Ridgely's	Delight histo	oric dist	trict. Ridgely	
Date of c	construction (if known): c. 1850	Original site	_ O Moved O C	late of allera	tions (if know the)	
4. Name an	d Mailing Address of Owner:					
Name _	Philip Sigel and Ralph Ma	inus				
Street _	315 South Beverly Drive,	Suite 502				
City	Beverly Hills		State	CA	_ Zip Code _90212	
Telepho	ne number (during day). Area Code(213) 277-7382				
			50 800 800	2000	20° 12 20 10 6	
I hereby att	est that the information I have provided is to	the best of my knowledge.	correct, and that I am	owner of the	properly described above	
	₫ 4 3	S: 1 >	inuite		Date	
Signature	y Number or Taxpayer Identification Numb	P. Sigel		Manus	GENCENTED).	
	MINERAL COLUMN SERVICE SE CONTRACTOR DE TRACTOR DE CONTRACTOR DE CONTRAC		PERCENTERS DE L'ANGE MANT		PROFESSIONAL PROFE	
	described above is included within the bound	dayler of a Decistored Utilia	in Descriptions	ntributer [1 dear sale calc business	
the character		uaries di a negisierea nista	TEDISINETANO DE	intributes L	1 coestion commodie to	
	□ appears □ does not appear to meet Na the National Register in accord with the De				vill likely D will not be	
and Dapper	is located in a district which appears. It will not be nominated to the National ars. On does not appear to contribute to a substantially meeting National Register contributions.	I Register in accord with the character of said dist	Department of the	Interior pro	cedures (36 CFR 60).	
Signature					Date	
	State Historic Preservation Officer					

is flot "A" mitched and is covered with numbed the shingles on the front section of the house. The roof on the rear section of the house is flat and is covered with tar and paper.

The window frames on the front facade are arched with a bullnose construction.

Third floor windows are slightly smaller than those on the second floor.

The entrance is a store front with a metal cornice overhang. The entrance is on the diagonal, facing northwest. The picture windows are completely missing. The cornice has a sculptured facing with lint.els.

The side facade also has a store front entrance. There is a badly deteriorated

wooden cornice over the door. Windows and doors are missing.

The interior of the house was wood framed with plaster walls and wood trim. The first floor consisted of a store area in the front and a bathroom and kitchen in the rear. There was a rear stairwell. The second floor consists of two rooms and one bath. The third floor consists of three connected rooms. On the second and third levels, the rear sections are elevated by one to two risers.

This building had undergone partial rehab before the certification process was begun. Therefore, we do not have interior photographs. The condition of the

unit, however, is substantiated by the engineering report.

. An engineering report documenting these conditions is forthcoming.

PART I #3

and has already been certified as a municipal historic district.

Originally, the area of Ridgely's Delight sprang up around a Susquehanoch Indian trail. Early settlers stamped a path though the area that connected it to the colonies to the north and south.

In 1714, a survey was undertaken for a Mr. John Parrish on a tract of land named Brotherly Love. Col. Charles Ridgely resurveyed Brotherly Love in 1732 and combined it with several other tracts of land. One of the tracts was Howard's Timber Neck, which Ridgely's wife Rachel had received as an inheritance from her grandfather, the original patentee (1668). Fremont Avenue was a part of Howard's Timber Neck, which was combined with other tracts to form Ridgely's Delight.

601 S. Fremont Avenue is very typical of the federal and Italianante store front style houses that characterized the neighborhood. An important architectural feature of the house is its diminshing window size. This feature can be found on many of the houses in the Ridgely district.

This house sits near the western border of the Ridgely district. From Martin Luther King Jr. Boulevard, the house is very visible and as this thoroughfare is widely used by both Baltimoreeans and "out-of-towners," the location and condition of the house is important to the entire district.

B-4073 601 S. Fremont Ave Block 861 Lot 038 Baltimore City Baltimore West Quad.

